








1






# 2




3





4





5






6





7





8





9







# 10





# 11





# 12






# 13





# 14





# 15





# 16





# 17






# 18





# 19





# 20




# 21





# 22






# 23






# 24





# 25





# 26




# 27



# 28



# 29



# 30

Connect  
Medium Motor  
to Port A

